

Yield reports

6 1/2" dia bore drilled at
BBMP ward 9, Narasipura tank

Yield test was carried out
and found to be 3"


Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97


ME W-09



Yield report

6 1/2" dia bore drilled at
BBMP Under no: 9, HM Layout
5th cross. Viriyangur.

Yield test was carried out at
tube 3"

MEG
[Signature]

Assistant Executive Engineer
Vidyananyapura Sub Division
BBMP, Bangalore - 97


[Signature]

12-10-09

[Signature]

yield report

6 1/2" dia. borewell drilled at BBMP
ind no: 9, Basara Sanithi layout.
yield test was carried out and
found to be 2 1/2"



Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97



AE W-09